

10000

Item #: 5634

Vehicle type:	Sonstiges
Condition of vehicle:	gebraucht
Type of superstructure:	Tank
Superstructure manufacturer:	ABO
Total tank volume:	10.000 liter
Number of tank chambers:	3
Tank volume chamber 1:	3.000 liter
Tank volume chamber 2:	3.500 liter
Tank volume chamber 3:	3.500 liter
Reception system:	ja
Name of reception system:	Abo Saug- und Messanlage
CIP-cleaning:	ja

