

12000

Item #: 5002

Vehicle type:	Sonstiges
Condition of vehicle:	gebraucht
Type of superstructure:	Tank
Superstructure manufacturer:	HLW
Total tank volume:	12.000 liter
Number of tank chambers:	3
Tank volume chamber 1:	4.000 liter
Tank volume chamber 2:	4.000 liter
Tank volume chamber 3:	4.000 liter
Reception system:	ja
Name of reception system:	HLW Turbo
Data processing:	MAK 3002 Plus
Sampling:	Sampler Probe
CIP-cleaning:	ja

